Town Name	Road Name	Route	Bridge Number	Map #	Link to Town Highway Bridge Report	Modified Rank by Program (with THB RPC)	RPC Pre- Candidate Ranking 2019	RPC Pre- Candidate Added Ranking Points 2019	CVRPC Approved Pre- Candidate Ranking 2020	CVRPC Notes	Average Daily Traffic	Facility Carried	Features Intersected	Location	Bridge Type	StrNum
MONTPELIER	State Street	USBR2	0B2-1	1	http://crashweb.vtransweb.aot.state.vt. us/VTransparency/ViewReport.aspx?rpt =RecordID&RecordID=1442&Type=struc turesL	57	2	13.50000		Bridge ranking has moved from 46 to 57. Montpelier is still working hard at maintaining this bridge and has made all the temporary fixes they can. The only option left is a replacement or full rehabilitiation.	006000	US 00BR2 BUS.	NORTH BRANCH	0.1 MI W JCT VT 12	CONC ENCASE D RIV GIR	206400B2-112112
MONTPELIER	Granite Street	GRNIT	00017	2	http://crashweb.vtransweb.aot.state.vt. us/VTransparency/ViewReport.aspx?rpt =RecordID&RecordID=2421&Type=struc turesL	22	3	12.00000		No rank last year but now 22. Vtrans reports the bridge is in fair condition with corrosion to superstructure that will need replacement in the future. Membrance should be installed on top of deck along with new asphalt to prevent futher leakage.		CITY GRNIT	WINOOSKI RIVER	GRANITE STREET	STEEL THRU TRUSS	206416001712112
DUXBURY	Camels Hump Rd	C3012	00037	3	http://crashweb.vtransweb.aot.state.vt. us/VTransparency/ViewReport.aspx?rpt =RecordID&RecordID=5770&Type=struc turesL	151		0.00000		Did not rank last year, but 151 now. Vtrans reports the bridge overall in satisfactory condition.	000200	C3012	RIDLEY BROOK	0.5 MI TO JCT W CL3 TH5	ROLLED BEAM	1.01206E+14
MONTPELIER	Grout Rd	C30GR	00015	4	http://crashweb.vtransweb.aot.state.vt. us/VTransparency/ViewReport.aspx?rpt =RecordID&RecordID=5841&Type=struc turesL	59	4	10.50000		Bridge ranking has moved from 80 to 59. Vtrans reports the bridge is in need of full replacement or major rehab.	000050	C30GR	N. BR. WINOOSKI RIVER	0.03 MI TO JCT W CL1 TH5	RLD BM W TIMBER DK	101211001512111
MORETOWN	Moretown Mtn Rd	C2001	00021	5	http://crashweb.vtransweb.aot.state.vt. us/VTransparency/ViewReport.aspx?rpt =RecordID&RecordID=5844&Type=struc turesL	42	5	9.00000		Bridge ranking has moved from 67 to 42. It is undersized and has scour under the bridge abutments. It is a priority for the town in the next 3-5 years for repair and/or replacement	000250	C2001	COX BROOK	@ JCT W CL4 TH47	ROLLED BEAM	101212002112121
MARSHFIELD	Onion River Rd	C3057	00027	6	http://crashweb.vtransweb.aot.state.vt. us/VTransparency/ViewReport.aspx?rpt =RecordID&RecordID=6032&Type=struc turesL	80	6	7.50000		Bridge ranking has not changed 80. Vtrans reports bridge is in fair condition but due to deck deterioration recommends full deck or superstructure replacement	000100	C3057	WINOOSKI RIVER	0.03 MI TO JCT W US2	ROLLED BEAM	101209002712091
NORTHFIELD	Stony Brook Rd	C3008	00047	7	http://crashweb.vtransweb.aot.state.vt. us/VTransparency/ViewReport.aspx?rpt =RecordID&RecordID=5591&Type=struc turesL	123	7	6.00000		Bridge ranking has moved from 70 to 123. It is in fair condition. Vtrans notes the structure will need rehab or replacement in the near future.	000400	C3008	DOG RIVER	@ JCT W VT12A	ROLLED BEAM	101213004712131
NORTHFIELD	Rabbit Hollow Rd	C3057	00065	8	http://crashweb.vtransweb.aot.state.vt. us/VTransparency/ViewReport.aspx?rpt =RecordID&RecordID=5601&Type=struc turesL	127	8	4.50000		Bridge ranking has moved from 74 to 127. Bridge is owned by Rail Road	000150	C3057	N.E.C.R.R. & DOG RIVER	0.1 MI TO JCT W VT12A	STEEL PONY TRUSS	101213006512131
FAYSTON	N Fayston Rd	C2001	00006	g	http://crashweb.vtransweb.aot.state.vt. us/VTransparency/ViewReport.aspx?rpt =RecordID&RecordID=5774&Type=struc turesL	114	9	3.00000		Bridge ranking has moved from 63 to 114. Vtrans notes the structure will need major rehab or replacement in the very near future	000500	C2001	SHEPARD BROOK	1.0 MI TO JCT W CL3 TH9	CONCRE TE T- BEAM	101208000612081
WAITSFIELD	East Rd	C3010	00021	10	http://crashweb.vtransweb.aot.state.vt. us/VTransparency/ViewReport.aspx?rpt =RecordID&RecordID=5884&Type=struc turesL	108	10	1.50000		Did not rank last year, but 108 now. Vtrans reports the bridge superstructure is in very good condition but that the deck should be replaced in the new future.	000010	C3010	PINE BROOK	0.10 MI E TO JCT W TH16		101216002112161

## Town Highway Bridge Pre-Candidate List

-		•	-	•		•	1. The impact of the pro	ject on congestion	and mobility conditions in the region (max 10pts.)	2. Availability, accessibility and useability of alternative routes (Max 10 pts.)
Town Name	Road Name	Deck Rating	Supstr Rating	Substr Rating	Culv Rating	Bypass Length	Will the project significantly improve a congestion problem?	Is the project located in a corridor projected for high AADT growth by	Importance of the project on a state of local highway network?	Are there alternative routes to get around a problem area?
	State Street	5	5	5	Z	01	0	1	2	5
	Granite Street	5	5	6	N	02	0	0	0	2
	Camels Hump Rd	6	6	5	Z	99	0	0	0	10
MONTPELIER	Grout Rd	6	5	5	N	99	0	0	0	10
	Moretown Mtn Rd	6	6	5	N	27	0	0	1	10
	Onion River Rd	5	5	6	N	99	0	0	0	10
	Stony Brook Rd	5	5	5	N	05	0	0	0	5
NORTHFIELD	Rabbit Hollow Rd	5	5	5	N	05	0	0	0	5
FAYSTON	N Fayston Rd	5	5	5	N	04	0	0	1	5
WAITSFIELD	East Rd	5	8	7	N	99	0	0	0	

3. Fuctional Importance as a link in the local, regional or state economy (Max. - 10 pts.)

4. Functional importance in the social and cultural life of surrounding communities (Max. - 10 pts.)

Town Name	Road Name	Does the project support the exisitng economy?	Is the project important for projected 2021 economic development?	Is the project within a commercial, Industrial or mixed use zone?	Important to access a school, shopping, recreation area, health care or other institutions?	Enhance/preserve a historical area/facility?	Improve bicycle & pedestrian facilities?	Improve the streetscape?	Provided traffic calming in cities or villages?	Support public transit/ridesha ring?
MONTPELIER	State Street	3	3	3	1	0	0	0	0	
MONTPELIER	Granite Street	2	3	3	1	0	0	0	0	0
DUXBURY	Camels Hump Rd	1	1	0	1	0	0	0	0	0
MONTPELIER	Grout Rd	1	3	0	0	0	0	0	0	0
MORETOWN	Moretown Mtn Rd	1	0	0	0	0	0	0	0	0
MARSHFIELD	Onion River Rd	1	0	0	0	0	0	0	0	0
NORTHFIELD	Stony Brook Rd	1	2	0	0	0	0	0	0	0
NORTHFIELD	Rabbit Hollow Rd	1	2	0	0	0	0	0	0	0
FAYSTON	N Fayston Rd	1	0	0	0	0	0	0	0	0
WAITSFIELD	East Rd	1	2	0	0	0	0	0	0	0

		5. Within a recognized growth area (Max 10 pts.)	6. Conformance to the Regional Plan	7. Local Support for the project (Max 10 pts.)			
Town Name	Road Name	Use Growth Area Map defined in Regions Transportation Plan	Supported in the Town and/ or Regional Plan?	Selectboard &/ or Planning Commission supoort project?	Is there an organized group or neighboring community opposing the project?	Regional Criteria Priority Score	Draft Ranking
MONTPELIER	State Street	10	0	0	0	28	1
MONTPELIER	Granite Street	10	0	0	0	21	2
DUXBURY	Camels Hump Rd	2	5	0		20	3
MONTPELIER	Grout Rd	0	0	0	0	14	4
MORETOWN	Moretown Mtn Rd	0	0	0	0	12	5
MARSHFIELD	Onion River Rd	0	0	0	0	11	6
NORTHFIELD	Stony Brook Rd	0	0	0	0	8	7
	Rabbit Hollow Rd	0	0	0	0	8	8
FAYSTON	N Fayston Rd	0	0	0	0	7	9
WAITSFIELD	East Rd	0	0	0	0	3	10